


MulTEA Demonstration Building (Sample Building 0): Three-story Walkup with Slab-on-grade Floor (06/22/2017)



Site Plan



Front View



Layout of a Dwelling Unit

Existing Building Description

General Characteristics

- Located in a suburban area in Boston, MA
- Box-shape, 7,740 sq ft, three-story building on slab-on-grade floor
- Six units (two units per floor)
- Double-loaded, enclosed, unconditioned hallways (including the stairwell)
- 12 occupants, with 3 occupants home during daytime
- Located on a lot having old asphalt ground surface

Walls

- All walls (exterior and partition) constructed with 8" hollow concrete blocks
- Stucco finish with medium-dark color on the exterior walls

Windows

- A 60"x48" (W1) and four 36"x48" (W2) windows in each unit; no window in hallways
- All windows are vertical slider with single-pane, clear glass, wood frame, and default leakage
- Each window has blinds

Doors

- Building entrance door in the hallway on first floor
 - o 42" x 80" hinged, hollow core, steel door with default leakage
 - o 20% of door is single-pane glass
- Apartment entrance doors (opening to the hallway; not to be modeled)
 - o 36" x 78" hinged, solid core wood door with default leakage

Roof/Ceiling

- A 3.75' high attic roof with 3/12 slope over the second floor
- 2x6 @ 24" wood-frame construction
- 3" normal density, fiberglass batt ceiling insulation
- Asphalt shingle roofing, dark color

Floor

• Uninsulated concrete, Slab-on-grade floor with 80% carpet

HVAC System

- A 5 kW electric baseboard heater, and a1.5 ton and a1 ton room air conditioners in each apartment
- No outside air ventilation associated with systems
- All systems manufactured and installed in 1998
- Default thermostat schedules (i.e., 68°F in heating mode and 76°F in cooling mode)

Infiltration

• 0.75 air changes per hour for the whole building

Water heaters

- A 40-gallon, 3 kW, electric, storage type water heater in each apartment
- All water heaters manufactured and installed in 1998
- Hot water supply temperature set at 130°F

Lighting

- An average of 0.5 watts/ sq ft in the building, with medium usage pattern
- 100 watts of exterior lighting

Appliances

• An average of 0.5 watts/ sq ft in apartments, with medium usage pattern

Utility Bills


Start date	End date	Whole-building electricity use (kWh)	Heating degree days (HDD65°F)	Cooling degree days (CDD65°F)
01/01/2013	01/31/2013	19,046	1,024	0
02/01/2013	02/28/2013	17,893	952	0
03/01/2013	03/31/2013	16,275	851	0
03/01/2013	04/30/2013	10,903	514	3
05/01/2013	05/31/2013	7,142	255	52
06/01/2013	06/30/2013	4,863	53	173
07/01/2013	07/31/2013	5,499	5	351
08/01/2013	08/31/2013	4,497	8	218
09/01/2013	09/30/2013	5,207	112	97
10/01/2013	10/31/2013	7,482	291	22
11/01/2013	11/30/2013	13,505	677	2
12/01/2013	12/31/2013	18,421	985	0

Retrofit Measures


- 1. Replace all windows (i.e., 6 W1 and 24 W2) with new double pane, low-e, high solar, vinyl frame windows
- 2. Replace building entrance door with a steel, polystyrene core door with 20% single pane glass
- 3. Add 6" normal density, blown cellulose ceiling insulation in the attic
- 4. Air seal the building to reduce whole-building air infiltration to 0.5 ACH
- 5. Replace 48-75 W incandescent lamps in apartments (8 lamps per apartment), operating 4 hours per day, with 23 W compact fluorescent lamps
- 6. Install 3 motion sensors in hallways (one per floor) to reduce the usage of 6-40 W fluorescent lamps (2 lamps per floor) from 24 hours per day to 4 hours per day
- 7. Replace six 18.5 cu ft existing refrigerators (1998 manufactured, top freezer, automatic defrost, and fair door seal condition) with new 18.5 cu ft refrigerators rated at 500 kWh annual energy use

MulTEA forms


Audit




Building




Walls




Walls (cont.)




Windows




Windows (cont.)




Doors




Roof




Floor




HVAC




HVAC (cont.)




HVAC (cont.)




Infiltration/Vent.




Water Heating




Lighting




Lighting (cont.)




Appliances/Eqpt.



Refrigerator



Utility Bills



MulTEA Building Audit Calibration Report

Report Printed on Thursday, June 22, 2017 at 2:35 p.m.

Agency Information

Agency: ORNL

Address: 1 Bethel valley Road

City: Oak Ridge

State: TN

Zip Code:

Phone Number: 8652416765

Account Information

Account Name: Sample Account 0

Account Number: \$0000

Other ID Number:

Address:

Unit:

City: Boston State: MA

Zip:

Comments: Three-story walkup with slab-on-grade floor

Audit Information

Audit Name: Sample Audit 0

Audit Number: 989

Auditor: ORNL LeadAuditor
Audit Date: June 9, 2017
Audit Created Date: June 9, 2017

Audit Comments: Three-story walkup with slab-on-grade floor

Audit Run Details


Version: 0.9


Weather Station: Boston Logan IntL Arpt


Weather State: MA
Building ID: 15058
Building Result ID: 2395


MulTEA Estimated Electricity Consumption (kWh)

			Hot			Building
Month	Heating	Cooling	Water	Appliances	Lighting	Total
January	15,170	0	1,249	2,602	1,374	20,395
February	11,470	0	1,145	2,351	1,241	16,207
March	10,286	0	1,242	2,603	1,374	15,506
April	5,022	10	1,141	2,518	1,254	9,945
May	1,014	238	1,093	2,602	1,296	6,243
June	18	1,103	975	2,519	1,254	5,870
July	0	2,758	946	2,602	1,296	7,602
August	0	2,157	923	2,602	1,296	6,978
September	0	787	914	2,519	1,254	5,474
October	959	61	1,006	2,602	1,374	6,002
November	5,977	0	1,055	2,520	1,330	10,882
December	11,555	0	1,176	2,603	1,374	16,709
Annual	61,471	7,114	12,866	30,643	15,719	127,813










Building Total Electricity Consumption Comparison (kWh)


	MulTEA		5	Percent
Month	Estimate	Utility Bill	Difference	Difference
January	20,395	19,046	1,349	7.1%
February	16,207	17,893	-1,686	-9.4%
March	15,506	16,275	-769	-4.7%
April	9,945	10,903	-958	-8.8%
May	6,243	7,142	-899	-12.6%
June	5,870	4,863	1,007	20.7%
July	7,602	5,499	2,103	38.2%
August	6,978	4,497	2,481	55.2%
September	5,474	5,207	267	5.1%
October	6,002	7,482	-1,480	-19.8%
November	10,882	13,505	-2,623	-19.4%
December	16,709	18,421	-1,712	-9.3%
Annual	127,813	130,733	-2,920	-2.2%

Usage Comparison (kWh)



Month	MulTEA HDD Estimate	Utility Bill HDD	Difference	Percent Difference	MulTEA CDD Estimate	Utility Bill CDD	Difference	Percent Difference
January	1,189	1,024	165	16.1%	0	0	0	NaN
February	950	952	-2	2%	0	0	0	NaN
March	813	851	-38	-4.5%	0	0	0	NaN
April	537	514	23	4.4%	9	3	6	200.0%
May	223	255	-32	-12.7%	30	52	-22	-41.5%
June	87	53	34	64.6%	116	173	-57	-32.8%
July	3	5	-2	-40.0%	284	351	-67	-19.0%
August	5	8	-3	-32.8%	192	218	-26	-11.9%
September	66	112	-46	-41.1%	53	97	-44	-44.9%
October	348	291	57	19.7%	9	22	-13	-60.5%
November	652	677	-25	-3.7%	0	2	-2	-100.0%
December	902	985	-83	-8.4%	0	0	0	NaN
Annual	5,776	5,727	49	.9%	694	918	-224	-24.4%

Heating and Cooling Degree Days Comparison



MulTEA Retrofit Measures Report

No Measure Interactions

AGENCY INFORMATION

Agency: ORNL

Address: 1 Bethel valley Road, P.O. Box 2008, Oak Ridge TN

Phone Number: 8652416765

Email: helpdesk@ornl.gov

ACCOUNT INFORMATION

Account Name: Sample Account 0

Account Number: S0000

Other ID Number:

Address: Boston MA

Comments: Three-story walkup with slab-on-grade floor

AUDIT INFORMATION

Audit Name: Sample Audit 0

Audit Number: 989

Auditor: ORNL_LeadAuditor

Audit Date: June 9, 2017

Last Edited On: June 22, 2017 2:05 PM

Comments: Three-story walkup with slab-on-grade floor

RETROFIT MEAURE RUN DETAILS

MulTEA Version: 0.1(build: 4967 rev: 23244:23672)

Calibration Run On: June 9, 2017 8:00 PM
Measures Run On: June 15, 2017 11:00 PM

Weather Station: Boston Logan IntL Arpt

Weather State: MA

Libraries:

Economic Parameters: Residential US Average - 2017

Measure Costs: Sample Buildings Measure Cost Library

Electricity: Average US Residential Electricity Costs - 2017 \$0.129/kWh
Natural Gas: Average US Residential Natural Gas Costs - 2017 \$9.9/Mcf

Propane: None Fuel Oil: None Kerosene: None

Agency: ORNL Audit Name: Sample Audit 0 Audit Number: 989

Ret	rofit Measure Energy Savings	(No Interaction A	mong Measures)										
				Predicted Annual Energy Savings									
				Electricity (kWh)						Fossil Fuel (MMBtu)			
#	Retrofit Measure	Component	Code	Heating	Cooling	Water Heating	Appliances and Equipment	Lighting	Total	Heating	Water Heating	Appliances and Equipment	Total
1	Replace Window	Windows	W1 60x48 windows	1,322	-88	0	0	0	1,234	0.00	0.00	0.00	0.00
2	Replace Window	Windows	W2 36x48 windows	3,665	-223	0	0	0	3,442	0.00	0.00	0.00	0.00
3	Replace Door	Doors	Building entrance door	20	0	0	0	0	20	0.00	0.00	0.00	0.00
4	Add Ceiling Insulation	Roofs	Attic roof	3,190	-1	0	0	0	3,189	0.00	0.00	0.00	0.00
5	Air Sealing	Infiltration/Ventilation	Infiltration	5,604	3	0	0	0	5,607	0.00	0.00	0.00	0.00
6	Replace Lamps	Lighting	Lamp Replacement	-1,822	411	0	0	3,644	2,234	0.00	0.00	0.00	0.00
7	Install Motion Sensors	Lighting	Hallway Motion Sensor	-613	126	0	0	2,102	1,616	0.00	0.00	0.00	0.00
8	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	-1,271	309	0	2,654	0	1,692	0.00	0.00	0.00	0.00

Ret	rofit Measure Cost Savings (N	lo Interaction Amo	ong Measures)								
				Predicted Annual Cost Savings (\$)							
#	Retrofit Measure	Component	Code	Heating	Cooling	Water Heating	Appliances and Equipment	Lighting	Total		
1	Replace Window	Windows	W1 60x48 windows	\$171	-\$11	\$0	\$0	\$0	\$159		
2	Replace Window	Windows	W2 36x48 windows	\$473	-\$29	\$0	\$0	\$0	\$444		
3	Replace Door	Doors	Building entrance door	\$3	\$0	\$0	\$0	\$0	\$3		
4	Add Ceiling Insulation	Roofs	Attic roof	\$412	\$0	\$0	\$0	\$0	\$411		
5	Air Sealing	Infiltration/Ventilation	Infiltration	\$723	\$0	\$0	\$0	\$0	\$723		
6	Replace Lamps	Lighting	Lamp Replacement	-\$235	\$53	\$0	\$0	\$470	\$288		
7	Install Motion Sensors	Lighting	Hallway Motion Sensor	-\$79	\$16	\$0	\$0	\$271	\$208		
8	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	-\$164	\$40	\$0	\$342	\$0	\$218		

Ret	rofit Measure Installation Cos	ts						
						Estimated Installation Cost		st (\$)
#	Retrofit Measure	Component	Code	Material Details	Retrofit Measure Cost Name	Default	Adjustment (+/-)	Final
1	Replace Window	Windows	W1 60x48 windows	Double Pane - Low-E, High Solar	Standard DP Low-E Window	\$3,888	\$0	\$3,888
2	Replace Window	Windows	W2 36x48 windows	Double Pane - Low-E, High Solar	Standard DP Low-E Window	\$12,096	\$0	\$12,096
3	Replace Door	Doors		Steel, Polystyrene Core - 20% Single Pane Glass	Standard Poly Steel Door	\$500	\$0	\$500
4	Add Ceiling Insulation	Roofs	Attic roof	Cellulose Blown - Normal Density	Cellulose Ceiling Insulation	\$3,870	\$0	\$3,870
5	Air Sealing	Infiltration/Ventilation	Infiltration		None Defined	\$0	\$2,000	\$2,000
6	Replace Lamps	Lighting	Lamp Replacement		23W CFL	\$288	\$0	\$288
7	Install Motion Sensors	Lighting	Hallway Motion Sensor		Standard Motion Sensor Kit	\$900	\$0	\$900
8	Replace the Refrigerator	Refrigerator	Refrigerator Replacement		Medium Replacement Refrigerator	\$2,700	-\$350	\$2,350

Retrofit N	leas	sure Economics (No Interactio	n Among Measure	es)					
Include in Package	#	Retrofit Measure	Component	Code	Predicted Annual Cost Savings (\$)	Estimated Installation Cost (\$)	Lifetime (years)	Savings-to-Investment Ratio (SIR)	Simple Payback Period (years)
No	1	Replace Window	Windows	W1 60x48 windows	\$159	\$3,888	20.0	0.66	24.4
No	2	Replace Window	Windows	W2 36x48 windows	\$444	\$12,096	20.0	0.59	27.2
No	3	Replace Door	Doors	Building entrance door	\$3	\$500	20.0	0.08	193.8
No	4	Add Ceiling Insulation	Roofs	Attic roof	\$411	\$3,870	20.0	1.71	9.4
No	5	Air Sealing	Infiltration/Ventilation	Infiltration	\$723	\$2,000	10.0	3.26	2.8
No	6	Replace Lamps	Lighting	Lamp Replacement	\$288	\$288	6.8	6.47	1.0
No	7	Install Motion Sensors	Lighting	Hallway Motion Sensor	\$208	\$900	12.0	2.45	4.3
No	8	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	\$218	\$2,350	15.0	1.19	10.8

MulTEA Retrofit Package Report

Measure Interactions Addressed

AGENCY INFORMATION

Agency: ORNL

Address: 1 Bethel valley Road, P.O. Box 2008, Oak Ridge TN

Phone Number: 8652416765

Email: helpdesk@ornl.gov

ACCOUNT INFORMATION

Account Name: Sample Account 0

Account Number: S0000

Other ID Number:

Address: Boston MA

Comments: Three-story walkup with slab-on-grade floor

AUDIT INFORMATION

Audit Name: Sample Audit 0

Audit Number: 989

Auditor: ORNL_LeadAuditor

Audit Date: June 9, 2017

Last Edited On: June 22, 2017 2:05 PM

Comments: Three-story walkup with slab-on-grade floor

RETROFIT PACKAGE RUN DETAILS

MulTEA Version: 0.1(build: 4967 rev: 23244:23672)

Calibration Run On:

June 9, 2017 8:00 PM

Measures Run On:

June 15, 2017 11:00 PM

Package Run On:

June 20, 2017 10:00 AM

Weather Station: Boston Logan IntL Arpt

Weather State: MA

Libraries:

Economic Parameters: Residential US Average - 2017

Measure Costs: Sample Buildings Measure Cost Library

Electricity: Average US Residential Electricity Costs - 2017 \$0.129/kWh
Natural Gas: Average US Residential Natural Gas Costs - 2017 \$9.9/Mcf

Propane: None
Fuel Oil: None
Kerosene: None

Agency: ORNL Audit Name: Sample Audit 0 Audit Number: 989

Ret	rofit Package Energy Savings	(Includes Interact	tion Among Measures)										
				Predicted Annual Energy Savings									
				Electricity (kWh)						Fossil Fuel (MMBtu)			
#	Retrofit Measure	Component	Code	Heating	Cooling	Water Heating	Appliances and Equipment	Lighting	Total	Heating	Water Heating	Appliances and Equipment	Total
1	Replace Lamps	Lighting	Lamp Replacement	-1,822	411	0	0	3,644	2,234	0.00	0.00	0.00	0.00
2	Air Sealing	Infiltration/Ventilation	Infiltration	5,627	8	0	0	0	5,635	0.00	0.00	0.00	0.00
3	Install Motion Sensors	Lighting	Hallway Motion Sensor	-570	126	0	0	2,102	1,658	0.00	0.00	0.00	0.00
4	Add Ceiling Insulation	Roofs	Attic roof	3,646	7	0	0	0	3,653	0.00	0.00	0.00	0.00
5	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	-1,270	313	0	2,654	0	1,697	0.00	0.00	0.00	0.00
6	Replace Window	Windows	W1 60x48 windows	1,536	-84	0	0	0	1,452	0.00	0.00	0.00	0.00
7	Replace Window	Windows	W2 36x48 windows	3,752	-223	0	0	0	3,529	0.00	0.00	0.00	0.00
8	Replace Door	Doors	Building entrance door	7	1	0	0	0	8	0.00	0.00	0.00	0.00
	Package			10,906	559	0	2,654	5,747	19,866	0.00	0.00	0.00	0.00

				Predicted Annual Cost Savings (\$)							
#	Retrofit Measure	Component	Code	Heating	Cooling	Water Heating	Appliances and Equipment	Lighting	Total		
1	Replace Lamps	Lighting	Lamp Replacement	-\$235	\$53	\$0	\$0	\$470	\$288		
2	Air Sealing	Infiltration/Ventilation	Infiltration	\$726	\$1	\$0	\$0	\$0	\$727		
3	Install Motion Sensors	Lighting	Hallway Motion Sensor	-\$74	\$16	\$0	\$0	\$271	\$214		
4	Add Ceiling Insulation	Roofs	Attic roof	\$470	\$1	\$0	\$0	\$0	\$471		
5	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	-\$164	\$40	\$0	\$342	\$0	\$219		
6	Replace Window	Windows	W1 60x48 windows	\$198	-\$11	\$0	\$0	\$0	\$187		
7	Replace Window	Windows	W2 36x48 windows	\$484	-\$29	\$0	\$0	\$0	\$455		
8	Replace Door	Doors	Building entrance door	\$1	\$0	\$0	\$0	\$0	\$1		
	Package	skage				\$0	\$342	\$741	\$2,563		

Ret	rofit Package Economics (Inc	ludes Interaction A	Among Measures)					
#	Retrofit Measure	Component	Code	Predicted Annual Cost Savings (\$)	Estimated Installation Cost (\$)	Lifetime (years)	Savings-to-Investment Ratio (SIR)	Simple Payback Period (years)
1	Replace Lamps	Lighting	Lamp Replacement	\$288	\$288	6.8	6.47	1.0
2	Air Sealing	Infiltration/Ventilation	Infiltration	\$727	\$2,000	10.0	3.27	2.8
3	Install Motion Sensors	Lighting	Hallway Motion Sensor	\$214	\$900	12.0	2.52	4.2
4	Add Ceiling Insulation	Roofs	Attic roof	\$471	\$3,870	20.0	1.96	8.2
5	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	\$219	\$2,350	15.0	1.19	10.7
6	Replace Window	Windows	W1 60x48 windows	\$187	\$3,888	20.0	0.77	20.8
7	Replace Window	Windows	W2 36x48 windows	\$455	\$12,096	20.0	0.60	26.6
8	Replace Door	Doors	Building entrance door	\$1	\$500	20.0	0.03	484.5
9	Fix Roof Leak - Attic Insulation			\$0	\$500	0.0	0.00	0.0
10	Repair roof (for Add Ceiling Insulation)			\$0	\$500	0.0	0.00	0.0
	Package			\$2,563	\$26,892		1.17	10.5

Ret	rofit Package Leveraging (Inc	ludes Interaction A	Among Measures)						
							Levera	aging	
#	Retrofit Measure	Component	Code	Estimated Installation Costs (\$)	Savings-to-Investment Ratio (SIR)	Buydown for SIR = 1.0 (\$)	Actual Buydown (\$)	Estimated Program Installation Cost (\$)	Program SIR
1	Replace Lamps	Lighting	Lamp Replacement	\$288	6.47	\$0	\$0	\$288	6.47
2	Air Sealing	Infiltration/Ventilation	Infiltration	\$2,000	3.27	\$0	\$0	\$2,000	3.27
3	Install Motion Sensors	Lighting	Hallway Motion Sensor	\$900	2.52	\$0	\$0	\$900	2.52
4	Add Ceiling Insulation	Roofs	Attic roof	\$3,870	1.96	\$0	\$0	\$3,870	1.96
5	Replace the Refrigerator	Refrigerator	Refrigerator Replacement	\$2,350	1.19	\$0	\$0	\$2,350	1.19
6	Replace Window	Windows	W1 60x48 windows	\$3,888	0.77	\$879	\$1,000	\$2,888	1.04
7	Replace Window	Windows	W2 36x48 windows	\$12,096	0.60	\$4,783	\$5,000	\$7,096	1.03
8	Replace Door	Doors	Building entrance door	\$500	0.03	\$483	\$0	\$500	0.03
9	Fix Roof Leak - Attic Insulation			\$500	0.00	\$0	\$0	\$500	0.00
10	Repair roof (for Add Ceiling Insulation)			\$500	0.00	\$0	\$0	\$500	0.00
	Package			\$26,892	1.17		\$6,000	\$20,892	1.50